



SECURITY GLASS STOREFRONTS

Laminated Polycarbonate

Exposed polycarbonate or spall shield surfaces require additional care to avoid damage and scratches. Do not use abrasive cleaners or cleaning products that can mar or gouge the surfaces. Wash polycarbonate surfaces with a mild soap or detergent and warm water, using a clean sponge or soft cloth. Rinse well with clean water. Dry thoroughly to prevent water spots.

Fresh paint splashes; grease, and smeared glazing compounds can be removed easily before drying by rubbing lightly with a quality grade isopropyl alcohol. Afterward, finish with a warm wash, using a mild soap or detergent solution and ending with a thorough rinsing with clean water.